

National Aeronautics and
Space Administration

Lyndon B. Johnson Space Center
White Sands Test Facility
P.O. Box 20
Las Cruces, NM 88004-0020



February 26, 2002

Reply to Attn of: RA-02-025

New Mexico Environment Department
Attn: Ms. Linda Montoya
Hazardous Waste Bureau
2905 Rodeo Park Drive East, Building 1
Santa Fe, NM 87505

Subject: 2001 Hazardous Waste Report for NASA JSC White Sands Test Facility (WSTF)

Enclosed are a signed IC Form, a hardcopy of the GM Form comments, and a 3.5-inch disk that contains the 2001 WSTF Hazardous Waste Report. If you have any questions or comments concerning this submittal, please call Michael Zigmond at 505-524-5484.

**ORIGINAL SIGNED BY
JOSEPH FRIES**

Joseph Fries
Manager

3 Enclosures

bcc:
HTSI Team/P. H. Pache (w/o encls.)

Commander (Encl. 1)
U.S. Army White Sands Missile Range
Attn: STEWS-NRES/T. A. Ladd
National Range Directorate, Environment and Safety
White Sands Missile Range, NM 88002

RA/MZigmond:ljg:2/26/02:5484

#4 zip LTRS\Env-02-1\Hazwarpt2001

CONCUR	CODE →	RA				
	SIGNATURE →	M. Zigmund				
	DATE →	2/16/02				

SENDER: COMPLETE THIS SECTION

- Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.
Print your name and address on the reverse so that we can return the card to you.
Attach this card to the back of the mailpiece, or on the front if space permits.

1. Article Addressed to:

NEW MEXICO ENVIRONMENT DEPARTMENT
ATTN: MS LINDA MONTOYA
HAZARDOUS WASTE BUREAU
2905 RODEO PARK DRIVE EAST BUILDING 1
SANTA FE NM 87505

COMPLETE THIS SECTION ON DELIVERY

- A. Received by (Please Print Clearly) Bamber Myte B. Date of Del 3-4-92
C. Signature [Signature] X ☐ Agent ☐ Addl ☐ Yes ☐ No
D. Is delivery address different from item 1? ☐ Yes ☐ No
If Yes, After delivery address below:

3. Service Type
☒ Certified Mail ☐ Express Mail
☐ Registered ☒ Return Receipt for Merchandise
☐ Insured Mail ☐ C.O.D.

4. Restricted Delivery? (Extra Fee) ☐ Yes

2. Article Number (Copy from service label)

9800 0600 0025 6710 2565

PS Form 3811, July 1999

Domestic Return Receipt

102595-00-M-0952

UNITED STATES POSTAL SERVICE

First-Class Mail
Postage & Fees Paid
USPS
Permit No. G-10

L-1 G

#025


• Sender: Please print your name, address, and ZIP+4 in this box •

Office of Aeronautics and
Space Administration

Revised Sept 82

Mail Code:
Lyndon B. Johnson Space Center
White Sands Test Facility
Post Office Box 20
Las Cruces, NM 88004-0020

88004-0020



MAIL THE COMPLETED FORM TO: The Appropriate EPA Regional or State Office	United States Environmental Protection Agency RCRA SUBTITLE C SITE IDENTIFICATION FORM		
1. Reason for Submittal and Status of Information Supplied (see instructions on pages 10 and 11) CHECK CORRECT BOX(ES)	A. Reason for Submittal: <input type="checkbox"/> To provide initial notification (to obtain an EPA ID Number for hazardous waste, universal waste, or used oil activities). <input type="checkbox"/> To provide subsequent notification (to update site identification information). <input type="checkbox"/> As a component of a First RCRA Hazardous Waste Part A Permit Application. <input type="checkbox"/> As a component of a Revised RCRA Hazardous Waste Part A Permit Application (Amendment # _____). <input checked="" type="checkbox"/> As a component of the Hazardous Waste Report.		
2. Site EPA ID Number (see instructions on page 11)	EPA ID Number: NM8800019434		
3. Site Name (see instructions on page 11)	Name: NASA JSC WHITE SANDS TEST FACILITY		
4. Site Location Information (see instructions on page 11)	Street Address: 12600 NASA ROAD		
	City, Town, or Village: LAS CRUCES	State: NM	
	County Name: DONA ANA	Zip Code: 88012- -	
5. Site Land Type (see instructions on page 11)	Site Land Type: <input type="checkbox"/> Private <input type="checkbox"/> County <input type="checkbox"/> District <input checked="" type="checkbox"/> Federal <input type="checkbox"/> Indian <input type="checkbox"/> Municipal <input type="checkbox"/> State <input type="checkbox"/> Other		
6. North American Industry Classification System (NAICS) Code(s) for the Site (see instructions on page 11)	A. 927110		B.
	C.		D.
7. Site Mailing Address (see instructions on page 12)	Street Address: P.O. BOX 20		
	City, Town, or Village: LAS CRUCES		
	State: NM		
	Country:	Zip Code: 88004- -	
8. Site Contact Person (see instructions on page 12)	First Name: MICHAEL	MI: J	Last Name: ZIGMOND
	Phone Number: (505) 524-5484		Phone Number Extension: 5484
9. Legal Owner and Operator of the Site (see instructions on pages 12 and 13)	A. Name of Site's Legal Owner: NASA JSC WHITE SANDS WHITE FACILITY		Date Became Owner (mm/dd/yyyy): 07/23/1962
	Owner Type: <input type="checkbox"/> Private <input type="checkbox"/> County <input type="checkbox"/> District <input checked="" type="checkbox"/> Federal <input type="checkbox"/> Indian <input type="checkbox"/> Municipal <input type="checkbox"/> State <input type="checkbox"/> Other		
	B. Name of Site's Operator: NASA JSC WHITE SANDS TEST FACILITY		Date Became Operator (mm/dd/yyyy): 07/23/1962
	Operator Type: <input type="checkbox"/> Private <input type="checkbox"/> County <input type="checkbox"/> District <input checked="" type="checkbox"/> Federal <input type="checkbox"/> Indian <input type="checkbox"/> Municipal <input type="checkbox"/> State <input type="checkbox"/> Other		

10. Type of Regulated Waste Activity (Mark 'X' in the appropriate boxes. See instructions on pages 13, 14, 15, and 16)**A. Hazardous Waste Activities****1. Generator of Hazardous Waste**

(choose only one of the following three categories)

- ☒ a. LQG: Greater than 1,000 kg/mo (2,200 lbs.) of non-acute hazardous waste; or
- ☐ b. SQG: 100 to 1,000 kg/mo (220 - 2,200 lbs.) of non-acute hazardous waste; or
- ☐ c. CESQG: Less than 100 kg/mo of non-acute hazardous waste

In addition, indicate other generator activities
(check all that apply)

- ☐ d. United States Importer of Hazardous Waste
- ☐ e. Mixed Waste (hazardous and radioactive) Generator

For Items 2 through 6, check all that apply:

- ☐ 2. Transporter of Hazardous Waste
- ☒ 3. Treater, Storer, or Disposer of Hazardous Waste (at your site) Note: A hazardous waste permit is required for this activity
- ☐ 4. Recycler of Hazardous Waste (at your site) Note: A hazardous waste permit may be required for this activity.
5. Exempt Boiler and/or Industrial Furnace
- ☐ a. Small Quantity On-site Burner Exemption
- ☐ b. Smelting, Melting, Refining Furnace Exemption
- ☐ 6. Underground Injection Control

B. Universal Waste Activities

1. Large Quantity Handler of Universal Waste [refer to your State regulations to determine what is regulated]. Indicate types of universal waste generated and/or accumulated at your site. (check all boxes that apply):

	Generated	Accumulated
a. Batteries	<input type="checkbox"/>	<input type="checkbox"/>
b. Pesticides	<input type="checkbox"/>	<input type="checkbox"/>
c. Thermostats	<input type="checkbox"/>	<input type="checkbox"/>
d. Lamps	<input type="checkbox"/>	<input type="checkbox"/>
e. Other (specify) _____	<input type="checkbox"/>	<input type="checkbox"/>
f. Other (specify) _____	<input type="checkbox"/>	<input type="checkbox"/>
g. Other (specify) _____	<input type="checkbox"/>	<input type="checkbox"/>

2. Destination Facility for Universal Waste ☐

Note: A hazardous waste permit may be required for this activity.

C. Used Oil Activities**1. Used Oil Transporter - Indicate Type(s) of Activity(ies)**

- ☐ a. Transporter
- ☐ b. Transfer Facility

2. Used Oil Processor and/or Re-refiner - Indicate Type(s) of Activity(ies)

- ☐ a. Processor
- ☐ b. Re-refiner

☐ **3. Off-Specification Used Oil Burner****4. Used Oil Fuel Marketer - Indicate Type(s) of Activity(ies)**

- ☐ a. Marketer Who Directs Shipment of Off-Specification Used Oil to Off-Specification Used Oil Burner
- ☐ b. Marketer Who First Claims the Used Oil Meets the Specifications

11. Description of Hazardous Wastes (see instructions on page 16)**A. Waste Codes for Federally Regulated Hazardous Wastes.**

Please list the waste codes of the Federal hazardous wastes handled at your site.

List them in the order they are presented in the regulations (e.g., D001, D003, F007, U112). Use an additional page if more spaces are needed.

D003	D001	D002	D006	D008	D007	D009
D011	D018	D027	D039	D040	D005	F001
F002	F004	F005	D035	U098	U133	U099
P068	F003					

EPA ID No. NM8800019434


B. Waste Codes for State-Regulated (i.e., non-Federal) Hazardous Wastes.

Please list the waste codes of the State-regulated hazardous wastes handled at your site. List them in the order they are presented in the regulations. Use an additional page if more spaces are needed for waste codes.

12. Comments (see instructions on page 17)

ATTACHED PLEASE FIND THE GM FORM COMMENTS REPRODUCED IN
HARDCOPY.

13. Certification. I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations. (see instructions on page 17)

Signature of owner, operator, or an authorized representative	Name and Official Title (type or print)	D. Date Signed (mm-dd-yyyy)
	JOSEPH FRIES MANAGER	02/25/2002

**NASA JSC WHITE SANDS TEST FACILITY
EPA ID NUMBER NM8800019434
COMMENTS HARDCOPY**

THE NASA WSTF INDIVIDUAL WASTE PROFILE SHEET (WIWPS) NUMBERS ADDED TO EACH GM FORM IS THE WASTE GENERATOR IDENTIFICATION/DESCRIPTION AND TRACKING INFORMATION WHICH, COMBINED WITH THE OFF-SITE MANIFESTS, PROVIDES THE INFORMATION USED TO COMPLETE THE FORM.

PAGE 1: WASTE CARBURETOR CLEANING COMPOUND (SAFETY-KLEEN)
NASA WIWPS# 10-01-08

PAGE 2: AQUEOUS BRAKE CLEANER (SAFETY-KLEEN)
ADDITIONAL CODE INFORMATION; FORM CODE; W219 AQUEOUS WASTE WITH LOW SOLVENTS.
NASA WIWPS# 10-01-15, 10-10-06

PAGE 3: OILY SLUDGE, STEAM PAD CLEANING DEBRIS
ADDITIONAL CODE INFORMATION: ADDITIONAL SOURCE CODE W609, WASTE GENERATED BY STEAM CLEANING EQUIPMENT AND FROM OIL/SLUDGE CLEAN-UPS.
NASA WIWPS# 10-01-11, 20-04-38, 80-04-13

PAGE 4: WASTE MACHINE SHOP LATHE AND SUMP OILS
NASA WIWPS# 10-02-02

PAGE 5: WASTE VACUUM PUMP OIL
NASA WIWPS# 10-06-09, 20-06-07, 20-07-04, 27-01-17, 30-02-06, 40-02-15, 80-01-07, 80-02-36, 80-02-62, 80-02-64, 80-03-09, 80-99103

PAGE 6: WASTE ORGANIC SOLVENTS
NASA WIWPS# 20-02-32, 20-01-40, 20-01-48, 20-01-48, 20-02-05 20-04-04, 20-04-12, 20-04-30, 20-04-33, 20-04-42, 20-04-48, 20-04-53, 20-04-54, 20-04-55, 20-04-69, 20-04-72, 20-08-04, 20-14-04, 20-99101, 30-02-18, 80-04-03

PAGE 7: FUEL CONTAMINATED SOFT GOODS
ADDITIONAL CODE INFORMATION: SOURCE CODE; G09 CLOTHING, PPE, RAGS, WIPES AND SOFT GOODS ASSOCIATED WITH SPACE SHUTTLE TESTING AND PARTS CLEANING CLEAN UP.
NASA WIWPS# 20-01-05, 20-04-18, 20-04-63, 20-04-76, 27-01-07, 30-01-08, 35-01-03, 40-01-08, 50-20-01, 80-02-09, 80-02-66

PAGE 8: CONTAMINATED REFUSE
ADDITIONAL CODE INFORMATION: SOURCE CODE; G09 RAGS, WIPES, BAGS, AND CLOTHING USED DURING CLEANING.
NASA WIWPS# 10-02-07, 10-03-03, 10-03-04, 10-20-01, 20-01,33, 20-02-22, 20-02-34, 20-04-40, 20-04-71, 20-02-72, 20-20-05-08, 20-06-09, 20-07-06, 20-15-02, 27-01-23, 30-01-06, 30-99101, 35-01-18, 40-02-56, 80-02-39, 80-04-09

PAGE 9: OXYGEN GENERATOR BY-PRODUCTS
ADDITIONAL CODE INFORMATION: SOURCE CODE; G09 OXYGEN GENERATOR METAL HOUSINGS, CONTAMINATED POST-TEST BY-PRODUCTS. FORM CODE; 319 OXIDIZER AND RCRA METAL CONTAMINATED BY-PRODUCTS.
NASA WIWPS# 80-02-59

PAGE 10: WASTE NICAD BATTERIES
NASA WIWPS# 10-20-10, 20-01-46, 20-02-25, 20-04-11, 20-13-07,30-01-20, 40-01-20

PAGE 11: WASTE PAINTS, INK, LACQUER, VARNISH, ADHESIVES, EPOXIES, AND THINNER
ADDITIONAL CODE INFORMATION: SOURCE CODE; G11 OFF-SPEC PRODUCTS. FORM
CODE; W409 CURED PAINTS AND ADHESIVES.

NASA WIWPS# 10-02-08, 10-03-01, 10-03-02, 10-04-08, 10-04-11 10-20-02, 10-20-05, 20-01-49,
20-08-03, 27-01-16, 20-99101, 30-01-13, 35-01-20, 35-01-32, 40-01-13

PAGE 12: WASTE ISOPROPYL ALCOHOL

NASA WIWPS# 20-01-05, 20-04-67, 35-01-05, 40-01-57, 40-02-08

PAGE 13: LEAD ACID BATTERIES

NASA WIWPS# 10-20-02, 20-04-60, 20-18-01, 40-01-59

PAGE 14: WASTE EXPLOSIVES

ADDITIONAL CODE INFORMATION: SOURCE CODE; G19 OFF-SPEC EXPLOSIVES.
MANAGEMENT OR DISPOSAL CODE; W409 OPEN DETONATION.

NASA WIWPS 70-01-01

PAGE 15: WASTE (HYDRAZINES) FUEL

ADDITIONAL CODE INFORMATION: FORM CODE; W219 WATERS WITH LOW ORGANIC
(METHYLHYDRAZINE) CONCENTRATIONS.

NASA WIWPS# 20-04-03, 20-04-49, 80-02-19, 80-02-60

PAGE 16: IGNITOR WASTE AND RINSE WATER

ADDITIONAL CODE INFORMATION: FORM CODE; W219 WATER WITH LOW ORGANIC
CONCENTRATIONS.

NASA WIWPS# 80-04-01

PAGE 17: WASTE AMMONIUM HYDROXIDE

NASA WIWPS# 80-04-01

PAGE 18: LITHIUM BATTERIES

GENERATED BUT NOT SHIPPED.

NASA WIWPS# 10-11-01, 10-20-09, 20-09-02

PAGE 19: SPENT OAKITE HD 126 CLEANING SOLUTION

NASA WIWPS# 20-01-11, 80-04-18

PAGE 20: SPENT OAKITE RUST STRIPPER CLEANING COMPOUND

NASA WIWPS# 20-01-13

PAGE 21: SPENT DERUSTIT CLEANING SOLUTION

NASA WIWPS# 20-01-22

PAGE 22: SPENT OAKITE 31 CLEANING SOLUTION

NASA WIWPS# 20-01-50, 80-04-17

PAGE 23: ACID DEOXIDIZER STAINLESS STEEL CLEANER

NASA WIWPS# 20-01-44

PAGE 24: OFF-SPEC HYDROGEN PEROXIDE

ADDITIONAL CODE INFORMATION: SOURCE CODE; G19 DISPOSAL OF HYDROGEN
PEROXIDE THAT NO LONGER MET TEST SPECIFICATION. FORM CODE; W119 90%
HYDROGEN PEROXIDE THAT WAS DILUTED TO <10%.

NASA WIWPS# 70-99001, 80-02-67

PAGE 25: SPENT PICKLING SOLUTION
NASA WIWPS# 20-01-14

PAGE 26: CITRIC ACID CLEANER
NASA WIWPS# 20-01-38

PAGE 27: ASPIRATED OXIDIZER IN WATER
ADDITIONAL CODE INFORMATION: SOURCE CODE; G09 NITRIC ACID IS GENERATED BY
ASPIRATION OF N2O4 INTO WATER.
NASA WIWPS# 30-01-04, 40-01-04

PAGE 28: OXIDIZER CONTAMINATED WATER
NASA WIWPS# 20-04-74, 30-01-02, 30-01-37, 40-01-02

PAGE 29: INORGANIC LABORATORY WASTE
ADDITIONAL CODE INFORMATION: FORM CODE; W119 INORGANIC LABORATORY WASTE
WITH POSSIBLE ACID, CAUSTIC, METAL AND DISSOLVED RESIDUALS GENERATED FROM
ROUTINE PROCEDURES AND EQUIPMENT CLEANUP.
NASA WIWPS# 20-04-65

PAGE 30: SPENT OAKITE 90 CLEANING SOLUTION
NASA WIWPS# 20-01-52

PAGE 31: SPENT ACIDIC CLEANING SOLUTION
NASA WIWPS# 20-01-41, 20-01-51

PAGE 32: PAGE DELETED WASTE WAS NOT GENERATED IN 2001.

PAGE 33: SPENT ECHANTS
NASA WIWPS# 20-02-01

PAGE 34: SPENT TINPOSIT SOLUTION LT-26
ADDITIONAL CODE INFORMATION: SOURCE CODE G06; COATING CIRCUIT BOARDS.
NASA WIWPS# 20-05-06

PAGE 35: SPENT X-RAY/PHOTOGRAPHIC FIXER SOLUTIONS
ADDITIONAL CODE INFORMATION: FORM CODE; W119 PHOTOGRAPHIC FILM DEVELOPING
FIXER SOLUTION WITH LESS THAN 75 PPM SILVER.
NASA WIWPS# 20-02-14, 20-03-12, 20-03-15, 20-03-25, 20-03-28, 20-03-31

PAGE 36: FUEL (HYDRAZINES) DILUTED IN WATER
ADDITIONAL CODE INFORMATION: SOURCE CODE; G19 SPACE SHUTTLE TESTING
PROPELLANT AQUEOUS WASTES GENERATED BY TEST ARTICLE AND PART
DECONTAMINATION, VAPOR VENTING, SCRUBBING, AND SAMPLING PROCESSES.
NASA WIWPS# 20-04-61, 30-01-01, 30-01-03, 30-01-33, 30-02-01, 35-01-01, 40-01-01, 40-01-03,
40-01-47, 80-02-04, 80-02-26, 80-02-28, 80-02-46, 80-02-61

PAGE 37: CYANIDE BEARING WASTE
ADDITIONAL CODE INFORMATION: FORM CODE; W119 CYANIDE IN CHEMICAL
STANDARDS IS NEUTRALIZED PRIOR TO ENTRY INTO THE PERMITTED HAZARDOUS
WASTE MANAGEMENT UNIT.
NASA WIWPS# 20-04-02

PAGE 38: PURGED GROUNDWATER

ADDITIONAL CODE INFORMATION: FORM CODE; W219 PURGED GROUNDWATER (RCRA INVESTIGATIVE DERIVED WASTE) WITH LOW CONCENTRATIONS OF EPA HAZARDOUS WASTE CODES F001 AND F002.

NASA WIWPS# 10-09-05

PAGE 39: MERCURY CONTAINED IN MANUFACTURED ARTICLES

ADDITIONAL CODE INFORMATION: SOURCE CODE; G053 CLEANUP OF SPILL RESIDUES. WASTE WAS GENERATED BUT NOT SHIPPED.

NASA WIWPS 10-04-05, 10-04-12, 20-02-19, 20-04-15, 20-10-02, 80-01-05

PAGE 40: MERCURY CONTAINING BATTERIES

WASTE WAS GENERATED BUT NOT SHIPPED.

NASA WIWPS# 10-20-14, 80-04-14

SITE NAME

NASA JSC WHITE SANDS TEST FACILITY
 NASA ROAD
 LAS CRUCES, NM 88012
 EPA ID NO: NM8800019434



U.S. ENVIRONMENTAL
 PROTECTION AGENCY
 2001 Hazardous Waste Report

FORM
 GM

WASTE GENERATION
 AND MANAGEMENT

Sec. 1	A. Waste Description WASTE CARBURETOR CLEANING COMPOUND (SAFETY-KLEEN)				
B. EPA Hazardous Waste Code D006 D008 D018 D027 D039 D040			C. State Hazardous Waste Code		
D. Source Code G01 Management Method Code for Source code G25		E. Form Code W203	F. RCRA radioactive mixed N	G. Quantity Generated in 2001 113.200000	H. UOM 3 Density 0.00 lb./gal.

Sec. 2	C. Was any of this waste managed on-site: No			
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2		
On-site Management Method code	Quantity treated, disposed, or recycled on-site in 2001	On-site Management Method code	Quantity treated, disposed, or recycled on-site in 2001	

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal, or recycling? Yes		
Site # 1	B. EPA ID No. of facility waste was shipped to TXD000747394	C. Off-site Management Method Code shipped to H141	D. Total quantity shipped in 2001 113.200000

Comments THE NASA WSTF INDIVIDUAL WASTE PROFILE SHEET (WIWPS) NUMBERS
 ADDED TO EACH GM FORM IS THE WASTE GENERATOR IDENTIFICATION

SITE NAME

NASA JSC WHITE SANDS TEST FACILITY

NASA ROAD

LAS CRUCES, NM 88012

EPA ID NO: NM8800019434

FORM
GMU.S. ENVIRONMENTAL
PROTECTION AGENCY
2001 Hazardous Waste ReportWASTE GENERATION
AND MANAGEMENT

Sec. 1	A. Waste Description AQUEOUS BRAKE CLEANER (SAFETY-KLEEN)				
B. EPA Hazardous Waste Code D039 D040			C. State Hazardous Waste Code		
D. Source Code G01 Management Method Code for Source code G25		E. Form Code W219	F. RCRA radioactive mixed N	G. Quantity Generated in 2001 153.800000	H. UOM 3 Density 0.00 lb./gal.
Sec. 2	C. Was any of this waste managed on-site: No				
ON-SITE PROCESS SYSTEM 1			ON-SITE PROCESS SYSTEM 2		
On-site Management Method code		Quantity treated, disposed, or recycled on-site in 2001		On-site Management Method code Quantity treated, disposed, or recycled on-site in 2001	
Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal, or recycling? Yes				
Site # 1	B. EPA ID No. of facility waste was shipped to TXD000747394	C. Off-site Management Method Code shipped to H141		D. Total quantity shipped in 2001 153.800000	
Comments ADDITIONAL CODE INFORMATION; FORM CODE; W219 AQUEOUS WASTE WITH LOW SOLVENTS. NASA WIWPS# 10-01-15, 10-10-06					

SITE NAME

NASA JSC WHITE SANDS TEST FACILITY
NASA ROAD
LAS CRUCES, NM 88012

EPA ID NO: NM8800019434



FORM
GM

U.S. ENVIRONMENTAL
PROTECTION AGENCY
2001 Hazardous Waste Report

WASTE GENERATION
AND MANAGEMENT

Sec. 1	A. Waste Description OILY SLUDGE, STEAM PAD CLEANING DEBRIS				
B. EPA Hazardous Waste Code D006 D008			C. State Hazardous Waste Code		
D. Source Code G01 Management Method Code for Source code G25		E. Form Code W603	F. RCRA radioactive mixed N	G. Quantity Generated in 2001 1,188.000000	H. UOM 3 Density 0.00 lb./gal.

Sec. 2	C. Was any of this waste managed on-site: No			
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2		
On-site Management Method code	Quantity treated, disposed, or recycled on-site in 2001	On-site Management Method code	Quantity treated, disposed, or recycled on-site in 2001	

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal, or recycling? Yes		
Site #	B. EPA ID No. of facility waste was shipped to	C. Off-site Management Method Code shipped to	D. Total quantity shipped in 2001
1	AZD049318009	H141	904.000000
2	ARD069748192	H040	284.000000

Comments	ADDITIONAL CODE INFORMATION: ADDITIONAL SOURCE CODE W609, WASTE GENERATED BY STEAM CLEANING EQUIPMENT AND FROM OIL/SLUD
----------	---

SITE NAME

NASA JSC WHITE SANDS TEST FACILITY
NASA ROAD
LAS CRUCES, NM 88012

EPA ID NO: NM8800019434



FORM
GM

U.S. ENVIRONMENTAL
PROTECTION AGENCY
2001 Hazardous Waste Report

WASTE GENERATION
AND MANAGEMENT

Sec. 1	A. Waste Description WASTE MACHINE SHOP LATHE AND SUMP OILS				
B. EPA Hazardous Waste Code D005 D007 D008			C. State Hazardous Waste Code		
D. Source Code G05 Management Method Code for Source code G25		E. Form Code W205	F. RCRA radioactive mixed N	G. Quantity Generated in 2001 2,639.000000	H. UOM 3 Density 0.00 lb./gal.
Sec. 2	C. Was any of this waste managed on-site: No				
ON-SITE PROCESS SYSTEM 1			ON-SITE PROCESS SYSTEM 2		
On-site Management Method code		Quantity treated, disposed, or recycled on-site in 2001	On-site Management Method code		Quantity treated, disposed, or recycled on-site in 2001
Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal, or recycling? Yes				
Site #	B. EPA ID No. of facility waste was shipped to	C. Off-site Management Method Code shipped to	D. Total quantity shipped in 2001		
1	ARD069748192	H040	1,500.000000		
2	AZD049318009	H141	1,139.000000		
Comments NASA WIWPS# 10-02-02					

SITE NAME

NASA JSC WHITE SANDS TEST FACILITY
 NASA ROAD
 LAS CRUCES, NM 88012
 EPA ID NO: NM8800019434



FORM
GM

U.S. ENVIRONMENTAL
 PROTECTION AGENCY
 2001 Hazardous Waste Report

WASTE GENERATION
 AND MANAGEMENT

Sec. 1	A. Waste Description WASTE VACUUM PUMP OIL				
B. EPA Hazardous Waste Code F001 F002 F003 F005			C. State Hazardous Waste Code		
D. Source Code G16 Management Method Code for Source code G25		E. Form Code W206	F. RCRA radioactive mixed N	G. Quantity Generated in 2001 1,401.000000	H. UOM 3 Density 0.00 lb./gal.
Sec. 2	C. Was any of this waste managed on-site: No				
ON-SITE PROCESS SYSTEM 1			ON-SITE PROCESS SYSTEM 2		
On-site Management Method code		Quantity treated, disposed, or recycled on-site in 2001	On-site Management Method code		Quantity treated, disposed, or recycled on-site in 2001
Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal, or recycling? Yes				
Site #	B. EPA ID No. of facility waste was shipped to	C. Off-site Management Method Code shipped to	D. Total quantity shipped in 2001		
1	ARD069748192	H040	476.000000		
2	AZD049318009	H141	925.000000		
Comments NASA WIWPS# 10-06-09, 20-06-07, 20-07-04, 27-01-17, 30-02-06, 40-02-15, 80-01-07, 80-02-36, 80-02-62, 80-02-64, 80-03-0					



U.S. ENVIRONMENTAL
PROTECTION AGENCY
2001 Hazardous Waste Report

SITE NAME

NASA JSC WHITE SANDS TEST FACILITY

NASA ROAD

LAS CRUCES, NM 88012

EPA ID NO: NM8800019434

**FORM
GM****WASTE GENERATION
AND MANAGEMENT**

Sec. 1	A. Waste Description WASTE ORGANIC SOLVENTS				
B. EPA Hazardous Waste Code D035 D001			C. State Hazardous Waste Code		
D. Source Code G22 Management Method Code for Source code G25		E. Form Code W203	F. RCRA radioactive mixed N	G. Quantity Generated in 2001 169.100000	H. UOM 3 Density 0.00 lb./gal.
Sec. 2	C. Was any of this waste managed on-site: No				
ON-SITE PROCESS SYSTEM 1			ON-SITE PROCESS SYSTEM 2		
On-site Management Method code		Quantity treated, disposed, or recycled on-site in 2001		On-site Management Method code Quantity treated, disposed, or recycled on-site in 2001	
Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal, or recycling? Yes				
Site # 1	B. EPA ID No. of facility waste was shipped to AZD049318009	C. Off-site Management Method Code shipped to H141		D. Total quantity shipped in 2001 169.100000	
Comments NASA WIWPS# 20-02-32, 20-01-40, 20-01-48, 20-01-48, 20-02-05 20-04-04, 20-04-12, 20-04-30, 20-04-33, 20-04-42, 20-04-48					

SITE NAME

NASA JSC WHITE SANDS TEST FACILITY
NASA ROAD
LAS CRUCES, NM 88012

EPA ID NO: NM8800019434



FORM
GM

U.S. ENVIRONMENTAL
PROTECTION AGENCY
2001 Hazardous Waste Report

WASTE GENERATION
AND MANAGEMENT

Sec. 1	A. Waste Description FUEL CONTAMINATED SOFT GOODS				
B. EPA Hazardous Waste Code P068 U133 U098 U099			C. State Hazardous Waste Code		
D. Source Code G09 Management Method Code for Source code G25		E. Form Code W002	F. RCRA radioactive mixed N	G. Quantity Generated in 2001 122.000000	H. UOM 3 Density 0.00 lb./gal.

Sec. 2	C. Was any of this waste managed on-site: No			
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2		
On-site Management Method code	Quantity treated, disposed, or recycled on-site in 2001	On-site Management Method code	Quantity treated, disposed, or recycled on-site in 2001	

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal, or recycling? Yes		
Site #	B. EPA ID No. of facility waste was shipped to	C. Off-site Management Method Code shipped to	D. Total quantity shipped in 2001
1	ARD069748192	H040	84.000000
2	AZD049318009	H141	38.000000

Comments	ADDITIONAL CODE INFORMATION: SOURCE CODE; G09 CLOTHING, PPE, RAGS, WIPES AND SOFT GOODS ASSOCIATED WITH SPACE SHUTTLE T
----------	---

SITE NAME

NASA JSC WHITE SANDS TEST FACILITY

NASA ROAD

LAS CRUCES, NM 88012

EPA ID NO: NM8800019434

FORM
GMU.S. ENVIRONMENTAL
PROTECTION AGENCY
2001 Hazardous Waste ReportWASTE GENERATION
AND MANAGEMENT

Sec. 1	A. Waste Description CONTAMINATED REFUSE				
B. EPA Hazardous Waste Code D008 D035			C. State Hazardous Waste Code		
D. Source Code G09 Management Method Code for Source code G25		E. Form Code W002	F. RCRA radioactive mixed N	G. Quantity Generated in 2001 283.900000	H. UOM 3 Density 0.00 lb./gal.
Sec. 2	C. Was any of this waste managed on-site: No				
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2			
On-site Management Method code		Quantity treated, disposed, or recycled on-site in 2001		On-site Management Method code Quantity treated, disposed, or recycled on-site in 2001	
Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal, or recycling? Yes				
Site #	B. EPA ID No. of facility waste was shipped to	C. Off-site Management Method Code shipped to	D. Total quantity shipped in 2001		
1	ARD069748192	H040	113.000000		
2	AZD049318009	H141	170.900000		
Comments ADDITIONAL CODE INFORMATION: SOURCE CODE; G09 RAGS, WIPES, BAGS, AND CLOTHING USED DURING CLEANING.					

SITE NAME

NASA JSC WHITE SANDS TEST FACILITY

NASA ROAD

LAS CRUCES, NM 88012

EPA ID NO: NM8800019434

FORM
GMU.S. ENVIRONMENTAL
PROTECTION AGENCY
2001 Hazardous Waste ReportWASTE GENERATION
AND MANAGEMENT

Sec. 1	A. Waste Description OXYGEN GENERATOR BY-PRODUCTS				
B. EPA Hazardous Waste Code D001 D005			C. State Hazardous Waste Code		
D. Source Code G09 Management Method Code for Source code G25		E. Form Code W319	F. RCRA radioactive mixed N	G. Quantity Generated in 2001 81.800000	H. UOM 3 Density 0.00 lb./gal.
Sec. 2	C. Was any of this waste managed on-site: No				
ON-SITE PROCESS SYSTEM 1			ON-SITE PROCESS SYSTEM 2		
On-site Management Method code			On-site Management Method code		
Quantity treated, disposed, or recycled on-site in 2001			Quantity treated, disposed, or recycled on-site in 2001		
Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal, or recycling? Yes				
Site # 1	B. EPA ID No. of facility waste was shipped to AZD049318009	C. Off-site Management Method Code shipped to H141		D. Total quantity shipped in 2001 81.800000	
Comments ADDITIONAL CODE INFORMATION: SOURCE CODE; G09 OXYGEN GENERATOR METAL HOUSINGS, CONTAMINATED POST-TEST BY-PRODUCTS. FOR					

SITE NAME

NASA JSC WHITE SANDS TEST FACILITY
 NASA ROAD
 LAS CRUCES, NM 88012
 EPA ID NO: NM8800019434



U.S. ENVIRONMENTAL
 PROTECTION AGENCY
 2001 Hazardous Waste Report

FORM
 GM

WASTE GENERATION
 AND MANAGEMENT

Sec. 1	A. Waste Description WASTE NICAD BATTERIES				
B. EPA Hazardous Waste Code D006			C. State Hazardous Waste Code		
D. Source Code G15 Management Method Code for Source code G25		E. Form Code W309	F. RCRA radioactive mixed N	G. Quantity Generated in 2001 231.000000	H. UOM 3 Density 0.00 lb./gal.
Sec. 2	C. Was any of this waste managed on-site: No				
ON-SITE PROCESS SYSTEM 1			ON-SITE PROCESS SYSTEM 2		
On-site Management Method code			On-site Management Method code		
Quantity treated, disposed, or recycled on-site in 2001			Quantity treated, disposed, or recycled on-site in 2001		
Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal, or recycling? Yes				
Site # 1	B. EPA ID No. of facility waste was shipped to ARD069748192	C. Off-site Management Method Code shipped to H040		D. Total quantity shipped in 2001 231.000000	
Comments NASA WIWPS# 10-20-10, 20-01-46, 20-02-25, 20-04-11, 20-13-07, 30-01-20, 40-01-20					

SITE NAME

NASA JSC WHITE SANDS TEST FACILITY
 NASA ROAD
 LAS CRUCES, NM 88012
 EPA ID NO: NM8800019434



U.S. ENVIRONMENTAL
 PROTECTION AGENCY
 2001 Hazardous Waste Report

FORM
 GM

WASTE GENERATION
 AND MANAGEMENT

Sec. 1	A. Waste Description WASTE PAINTS, INK, LACQUER, VARNISH, ADHESIVES, EPOXIES, AND THINNER				
B. EPA Hazardous Waste Code D001 D006 D007 D008 D009 D035			C. State Hazardous Waste Code		
D. Source Code G06 Management Method Code for Source code G25		E. Form Code W209	F. RCRA radioactive mixed N	G. Quantity Generated in 2001 1,007.000000	H. UOM 3 Density 0.00 lb./gal.

Sec. 2	C. Was any of this waste managed on-site: No	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method code	Quantity treated, disposed, or recycled on-site in 2001	On-site Management Method code
Quantity treated, disposed, or recycled on-site in 2001		Quantity treated, disposed, or recycled on-site in 2001

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal, or recycling? Yes		
Site #	B. EPA ID No. of facility waste was shipped to	C. Off-site Management Method Code shipped to	D. Total quantity shipped in 2001
1	ARD069748192	H040	622.000000
2	AZD049318009	H141	385.000000

Comments ADDITIONAL CODE INFORMATION: SOURCE CODE; G11 OFF-SPEC PRODUCTS. FORM CODE; W409 CURED PAINTS AND ADHESIVES. NASA WIWP

SITE NAME

NASA JSC WHITE SANDS TEST FACILITY

NASA ROAD

LAS CRUCES, NM 88012

EPA ID NO: NM8800019434

FORM
GMU.S. ENVIRONMENTAL
PROTECTION AGENCY
2001 Hazardous Waste ReportWASTE GENERATION
AND MANAGEMENT

Sec. 1	A. Waste Description WASTE ISOPROPYL ALCOHOL				
B. EPA Hazardous Waste Code D001			C. State Hazardous Waste Code		
D. Source Code G01 Management Method Code for Source code G25		E. Form Code W203	F. RCRA radioactive mixed N	G. Quantity Generated in 2001 596.400000	H. UOM 3 Density 0.00 lb./gal.

Sec. 2	C. Was any of this waste managed on-site: No			
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2		
On-site Management Method code	Quantity treated, disposed, or recycled on-site in 2001	On-site Management Method code	Quantity treated, disposed, or recycled on-site in 2001	

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal, or recycling? Yes		
Site #	B. EPA ID No. of facility waste was shipped to	C. Off-site Management Method Code shipped to	D. Total quantity shipped in 2001
1	ARD069748192	H040	186.400000
2	AZD049318009	H141	410.000000

Comments NASA WIWPS# 20-01-05, 20-04-67, 35-01-05, 40-01-57, 40-02-08

SITE NAME

NASA JSC WHITE SANDS TEST FACILITY
 NASA ROAD
 LAS CRUCES, NM 88012
 EPA ID NO: NM8800019434



U.S. ENVIRONMENTAL
 PROTECTION AGENCY
 2001 Hazardous Waste Report

FORM
 GM

WASTE GENERATION
 AND MANAGEMENT

Sec. 1	A. Waste Description LEAD ACID BATTERIES				
B. EPA Hazardous Waste Code D008			C. State Hazardous Waste Code		
D. Source Code G16 Management Method Code for Source code G25		E. Form Code W309	F. RCRA radioactive mixed N	G. Quantity Generated in 2001 355.500000	H. UOM 3 Density 0.00 lb./gal.
Sec. 2	C. Was any of this waste managed on-site: No				
ON-SITE PROCESS SYSTEM 1			ON-SITE PROCESS SYSTEM 2		
On-site Management Method code			On-site Management Method code		
Quantity treated, disposed, or recycled on-site in 2001			Quantity treated, disposed, or recycled on-site in 2001		
Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal, or recycling? Yes				
Site # 1	B. EPA ID No. of facility waste was shipped to ARD069748192	C. Off-site Management Method Code shipped to H040		D. Total quantity shipped in 2001 355.500000	
Comments NASA WIWPS# 10-20-02, 20-04-60, 20-18-01, 40-01-59					

SITE NAME

NASA JSC WHITE SANDS TEST FACILITY
 NASA ROAD
 LAS CRUCES, NM 88012

EPA ID NO: NM8800019434



U.S. ENVIRONMENTAL
 PROTECTION AGENCY
 2001 Hazardous Waste Report

FORM
 GM

WASTE GENERATION
 AND MANAGEMENT

Sec. 1	A. Waste Description WASTE EXPLOSIVES				
B. EPA Hazardous Waste Code D003			C. State Hazardous Waste Code		
D. Source Code G19 Management Method Code for Source code G25		E. Form Code W405	F. RCRA radioactive mixed N	G. Quantity Generated in 2001 1.700000	H. UOM 3 Density 0.00 lb./gal.
Sec. 2	C. Was any of this waste managed on-site: No				
ON-SITE PROCESS SYSTEM 1			ON-SITE PROCESS SYSTEM 2		
On-site Management Method code		Quantity treated, disposed, or recycled on-site in 2001		On-site Management Method code Quantity treated, disposed, or recycled on-site in 2001	
Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal, or recycling? Yes				
Site # 1	B. EPA ID No. of facility waste was shipped to LAD981055791	C. Off-site Management Method Code shipped to H129		D. Total quantity shipped in 2001 1.700000	
Comments ADDITIONAL CODE INFORMATION: SOURCE CODE; G19 OFF-SPEC EXPL OSIVES. MANAGEMENT OR DISPOSAL CODE; W409 OPEN DETONATION.					

SITE NAME

NASA JSC WHITE SANDS TEST FACILITY
NASA ROAD
LAS CRUCES, NM 88012

EPA ID NO: NM8800019434

**FORM
GM**

U.S. ENVIRONMENTAL
PROTECTION AGENCY
2001 Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Sec. 1	A. Waste Description WASTE (HYRDAZINES) FUEL				
B. EPA Hazardous Waste Code P068 U098 U133 U099			C. State Hazardous Waste Code		
D. Source Code G22 Management Method Code for Source code G25		E. Form Code W113	F. RCRA radioactive mixed N	G. Quantity Generated in 2001 5,866.800000	H. UOM 6 Density 1.00 spec.gra
Sec. 2	C. Was any of this waste managed on-site: Yes				
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2			
On-site Management Method code H122		Quantity treated, disposed, or recycled on-site in 2001 5,866.800000		On-site Management Method code *****	Quantity treated, disposed, or recycled on-site in 2001
Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal, or recycling? No				
Site #	B. EPA ID No. of facility waste was shipped to	C. Off-site Management Method Code shipped to	D. Total quantity shipped in 2001		
Comments ADDITIONAL CODE INFORMATION: FORM CODE; W219 WATERS WITH LO W ORGANIC (METHYLHYDRAZINE) CONCENTRATIONS. NASA WIWPS# 20-					

SITE NAME

NASA JSC WHITE SANDS TEST FACILITY

NASA ROAD

LAS CRUCES, NM 88012

EPA ID NO: NM8800019434

FORM
GMU.S. ENVIRONMENTAL
PROTECTION AGENCY
2001 Hazardous Waste ReportWASTE GENERATION
AND MANAGEMENT

Sec. 1	A. Waste Description IGNITOR WASTE AND RINSE WATER				
B. EPA Hazardous Waste Code D001			C. State Hazardous Waste Code		
D. Source Code G22 Management Method Code for Source code G25		E. Form Code W219	F. RCRA radioactive mixed N	G. Quantity Generated in 2001 94.600000	H. UOM 6 Density 1.00 spec.gra
Sec. 2	C. Was any of this waste managed on-site: Yes				
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2			
On-site Management Method code H122		Quantity treated, disposed, or recycled on-site in 2001 94.600000		On-site Management Method code Quantity treated, disposed, or recycled on-site in 2001 *****	
Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal, or recycling? No				
Site #	B. EPA ID No. of facility waste was shipped to	C. Off-site Management Method Code shipped to		D. Total quantity shipped in 2001	
Comments ADDITIONAL CODE INFORMATION: FORM CODE; W219 WATER WITH LOW ORGANIC CONCENTRATIONS. NASA WIWPS# 80-04-01					

SITE NAME

NASA JSC WHITE SANDS TEST FACILITY

NASA ROAD

LAS CRUCES, NM 88012

EPA ID NO: NM8800019434

FORM
GMU.S. ENVIRONMENTAL
PROTECTION AGENCY
2001 Hazardous Waste ReportWASTE GENERATION
AND MANAGEMENT

Sec. 1	A. Waste Description WASTE AMMONIUM HYDROXIDE				
B. EPA Hazardous Waste Code D002			C. State Hazardous Waste Code		
D. Source Code G07 Management Method Code for Source code G25		E. Form Code W110	F. RCRA radioactive mixed N	G. Quantity Generated in 2001 37.900000	H. UOM 6 Density 1.00 spec.gra
Sec. 2	C. Was any of this waste managed on-site: Yes				
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2			
On-site Management Method code H122		Quantity treated, disposed, or recycled on-site in 2001 37.900000		On-site Management Method code Quantity treated, disposed, or recycled on-site in 2001 *****	
Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal, or recycling? No				
Site #	B. EPA ID No. of facility waste was shipped to	C. Off-site Management Method Code shipped to		D. Total quantity shipped in 2001	
Comments NASA WIWPS# 80-04-01					

SITE NAME

NASA JSC WHITE SANDS TEST FACILITY

NASA ROAD

LAS CRUCES, NM 88012

EPA ID NO: NM8800019434

**FORM
GM**U.S. ENVIRONMENTAL
PROTECTION AGENCY
2001 Hazardous Waste Report**WASTE GENERATION
AND MANAGEMENT**

Sec. 1	A. Waste Description LITHIUM BATTERIES				
B. EPA Hazardous Waste Code D003			C. State Hazardous Waste Code		
D. Source Code G15 Management Method Code for Source code G25		E. Form Code W309	F. RCRA radioactive mixed N	G. Quantity Generated in 2001 11.400000	H. UOM 3 Density 0.00 lb./gal.
Sec. 2	C. Was any of this waste managed on-site: No				
ON-SITE PROCESS SYSTEM 1			ON-SITE PROCESS SYSTEM 2		
On-site Management Method code			On-site Management Method code		
Quantity treated, disposed, or recycled on-site in 2001			Quantity treated, disposed, or recycled on-site in 2001		
Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal, or recycling? No				
Site #	B. EPA ID No. of facility waste was shipped to	C. Off-site Management Method Code shipped to		D. Total quantity shipped in 2001	
Comments GENERATED BUT NOT SHIPPED. NASA WIWPS# 10-11-01, 10-20-09, 20-09-02					

SITE NAME

NASA JSC WHITE SANDS TEST FACILITY

NASA ROAD

LAS CRUCES, NM 88012

EPA ID NO: NM8800019434

FORM
GMU.S. ENVIRONMENTAL
PROTECTION AGENCY
2001 Hazardous Waste ReportWASTE GENERATION
AND MANAGEMENT

Sec. 1	A. Waste Description SPENT OAKITE HD 126 CLEANING SOLUTION				
B. EPA Hazardous Waste Code D002			C. State Hazardous Waste Code		
D. Source Code G02 Management Method Code for Source code G25		E. Form Code W110	F. RCRA radioactive mixed N	G. Quantity Generated in 2001 2,600.300000	H. UOM 6 Density 1.00 spec.gra
Sec. 2	C. Was any of this waste managed on-site: Yes				
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2			
On-site Management Method code H122		Quantity treated, disposed, or recycled on-site in 2001 2,600.300000		On-site Management Method code Quantity treated, disposed, or recycled on-site in 2001 *****	
Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal, or recycling? No				
Site #	B. EPA ID No. of facility waste was shipped to	C. Off-site Management Method Code shipped to		D. Total quantity shipped in 2001	
Comments NASA WIWPS# 20-01-11, 80-04-18					

SITE NAME

NASA JSC WHITE SANDS TEST FACILITY

NASA ROAD

LAS CRUCES, NM 88012

EPA ID NO: NM8800019434

FORM
GMU.S. ENVIRONMENTAL
PROTECTION AGENCY
2001 Hazardous Waste ReportWASTE GENERATION
AND MANAGEMENT

Sec. 1	A. Waste Description SPENT OAKITE RUST STRIPPER CLEANING COMPOUND				
B. EPA Hazardous Waste Code D002			C. State Hazardous Waste Code		
D. Source Code G02 Management Method Code for Source code G25		E. Form Code W110	F. RCRA radioactive mixed N	G. Quantity Generated in 2001 1,892.500000	H. UOM 6 Density 1.00 spec.gra
Sec. 2	C. Was any of this waste managed on-site: Yes				
ON-SITE PROCESS SYSTEM 1			ON-SITE PROCESS SYSTEM 2		
On-site Management Method code H122		Quantity treated, disposed, or recycled on-site in 2001 1,892.500000	On-site Management Method code *****		
Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal, or recycling? No				
Site #	B. EPA ID No. of facility waste was shipped to	C. Off-site Management Method Code shipped to	D. Total quantity shipped in 2001		
Comments NASA WIWPS# 20-01-13					



U.S. ENVIRONMENTAL
PROTECTION AGENCY
2001 Hazardous Waste Report

FORM
GM

WASTE GENERATION
AND MANAGEMENT

SITE NAME

NASA JSC WHITE SANDS TEST FACILITY

NASA ROAD

LAS CRUCES, NM 88012

EPA ID NO: NM8800019434

Sec. 1	A. Waste Description SPENT DERUSTIT CLEANING SOLUTION				
B. EPA Hazardous Waste Code D002			C. State Hazardous Waste Code		
D. Source Code G02 Management Method Code for Source code G25		E. Form Code W103	F. RCRA radioactive mixed N	G. Quantity Generated in 2001 18.900000	H. UOM 6 Density 1.00 spec.gra
Sec. 2	C. Was any of this waste managed on-site: Yes				
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2			
On-site Management Method code H122		Quantity treated, disposed, or recycled on-site in 2001 18.900000		On-site Management Method code Quantity treated, disposed, or recycled on-site in 2001 *****	
Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal, or recycling? No				
Site #	B. EPA ID No. of facility waste was shipped to	C. Off-site Management Method Code shipped to		D. Total quantity shipped in 2001	
Comments NASA WIWPS# 20-01-22					

SITE NAME

NASA JSC WHITE SANDS TEST FACILITY
NASA ROAD
LAS CRUCES, NM 88012
EPA ID NO: NM8800019434

**FORM
GM**

U.S. ENVIRONMENTAL
PROTECTION AGENCY
2001 Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Sec. 1	A. Waste Description SPENT OAKITE 31 CLEANING SOLUTION				
B. EPA Hazardous Waste Code D002			C. State Hazardous Waste Code		
D. Source Code G02 Management Method Code for Source code G25		E. Form Code W105	F. RCRA radioactive mixed N	G. Quantity Generated in 2001 7,910.700000	H. UOM 6 Density 1.00 spec.gra
Sec. 2	C. Was any of this waste managed on-site: Yes				
ON-SITE PROCESS SYSTEM 1			ON-SITE PROCESS SYSTEM 2		
On-site Management Method code H122		Quantity treated, disposed, or recycled on-site in 2001 7,910.700000		On-site Management Method code Quantity treated, disposed, or recycled on-site in 2001 *****	
Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal, or recycling? No				
Site #	B. EPA ID No. of facility waste was shipped to	C. Off-site Management Method Code shipped to		D. Total quantity shipped in 2001	
Comments NASA WIWPS# 20-01-50, 80-04-17					

SITE NAME

NASA JSC WHITE SANDS TEST FACILITY

NASA ROAD

LAS CRUCES, NM 88012

EPA ID NO: NM8800019434

FORM
GMU.S. ENVIRONMENTAL
PROTECTION AGENCY
2001 Hazardous Waste ReportWASTE GENERATION
AND MANAGEMENT

Sec. 1	A. Waste Description ACID DEOXIDIZER STAINLESS STEEL CLEANER				
B. EPA Hazardous Waste Code D002			C. State Hazardous Waste Code		
D. Source Code G02 Management Method Code for Source code G25		E. Form Code W105	F. RCRA radioactive mixed N	G. Quantity Generated in 2001 416.400000	H. UOM 6 Density 1.00 spec.gra
Sec. 2	C. Was any of this waste managed on-site: Yes				
ON-SITE PROCESS SYSTEM 1			ON-SITE PROCESS SYSTEM 2		
On-site Management Method code H122		Quantity treated, disposed, or recycled on-site in 2001 416.400000		On-site Management Method code ***** Quantity treated, disposed, or recycled on-site in 2001	
Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal, or recycling? No				
Site #	B. EPA ID No. of facility waste was shipped to	C. Off-site Management Method Code shipped to		D. Total quantity shipped in 2001	
Comments NASA WIWPS# 20-01-44					

SITE NAME

NASA JSC WHITE SANDS TEST FACILITY

NASA ROAD

LAS CRUCES, NM 88012

EPA ID NO: NM8800019434

FORM
GMU.S. ENVIRONMENTAL
PROTECTION AGENCY
2001 Hazardous Waste ReportWASTE GENERATION
AND MANAGEMENT

Sec. 1	A. Waste Description OFF-SPEC HYDROGEN PEROXIDE				
B. EPA Hazardous Waste Code D002			C. State Hazardous Waste Code		
D. Source Code G19 Management Method Code for Source code G25		E. Form Code W119	F. RCRA radioactive mixed N	G. Quantity Generated in 2001 7,573.800000	H. UOM 6 Density 1.00 spec.gra
Sec. 2	C. Was any of this waste managed on-site: Yes				
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2			
On-site Management Method code H122		Quantity treated, disposed, or recycled on-site in 2001 7,573.800000		On-site Management Method code *****	
Quantity treated, disposed, or recycled on-site in 2001		Quantity treated, disposed, or recycled on-site in 2001			
Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal, or recycling? No				
Site #	B. EPA ID No. of facility waste was shipped to	C. Off-site Management Method Code shipped to	D. Total quantity shipped in 2001		
Comments ADDITIONAL CODE INFORMATION: SOURCE CODE; G19 DISPOSAL OF H YDROGEN PEROXIDE THAT NO LONGER MET TEST SPECIFICATION. FOR					



U.S. ENVIRONMENTAL
PROTECTION AGENCY
2001 Hazardous Waste Report

FORM
GM

WASTE GENERATION
AND MANAGEMENT

Sec. 1	A. Waste Description SPENT PICKLING SOLUTION				
B. EPA Hazardous Waste Code D002			C. State Hazardous Waste Code		
D. Source Code G02 Management Method Code for Source code G25		E. Form Code W105	F. RCRA radioactive mixed N	G. Quantity Generated in 2001 189.300000	H. UOM 6 Density 1.00 spec.gra
Sec. 2	C. Was any of this waste managed on-site: Yes				
ON-SITE PROCESS SYSTEM 1			ON-SITE PROCESS SYSTEM 2		
On-site Management Method code H122		Quantity treated, disposed, or recycled on-site in 2001 189.300000		On-site Management Method code *****	
Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal, or recycling? No				
Site #	B. EPA ID No. of facility waste was shipped to	C. Off-site Management Method Code shipped to		D. Total quantity shipped in 2001	
Comments NASA WIWPS# 20-01-14					



U.S. ENVIRONMENTAL
PROTECTION AGENCY
2001 Hazardous Waste Report

SITE NAME

NASA JSC WHITE SANDS TEST FACILITY
NASA ROAD
LAS CRUCES, NM 88012

EPA ID NO: NM8800019434

FORM
GM

WASTE GENERATION
AND MANAGEMENT

Sec. 1	A. Waste Description CITRIC ACID CLEANER				
B. EPA Hazardous Waste Code D002			C. State Hazardous Waste Code		
D. Source Code G02 Management Method Code for Source code G25		E. Form Code W105	F. RCRA radioactive mixed N	G. Quantity Generated in 2001 3,785.000000	H. UOM 6 Density 1.00 spec.gra
Sec. 2	C. Was any of this waste managed on-site: Yes				
ON-SITE PROCESS SYSTEM 1			ON-SITE PROCESS SYSTEM 2		
On-site Management Method code H122		Quantity treated, disposed, or recycled on-site in 2001 3,785.000000		On-site Management Method code Quantity treated, disposed, or recycled on-site in 2001 *****	
Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal, or recycling? No				
Site #	B. EPA ID No. of facility waste was shipped to	C. Off-site Management Method Code shipped to		D. Total quantity shipped in 2001	
Comments NASA WIWPS# 20-01-38					

SITE NAME

NASA JSC WHITE SANDS TEST FACILITY

NASA ROAD

LAS CRUCES, NM 88012

EPA ID NO: NM8800019434

FORM
GMU.S. ENVIRONMENTAL
PROTECTION AGENCY
2001 Hazardous Waste ReportWASTE GENERATION
AND MANAGEMENT

Sec. 1	A. Waste Description ASPIRATED OXIDIZER IN WATER				
B. EPA Hazardous Waste Code D002			C. State Hazardous Waste Code		
D. Source Code G09 Management Method Code for Source code G25		E. Form Code W105	F. RCRA radioactive mixed N	G. Quantity Generated in 2001 567.800000	H. UOM 6 Density 1.00 spec.gra
Sec. 2	C. Was any of this waste managed on-site: Yes				
ON-SITE PROCESS SYSTEM 1			ON-SITE PROCESS SYSTEM 2		
On-site Management Method code H122		Quantity treated, disposed, or recycled on-site in 2001 567.800000		On-site Management Method code Quantity treated, disposed, or recycled on-site in 2001 *****	
Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal, or recycling? No				
Site #	B. EPA ID No. of facility waste was shipped to	C. Off-site Management Method Code shipped to		D. Total quantity shipped in 2001	
Comments ADDITIONAL CODE INFORMATION: SOURCE CODE; G09 NITRIC ACID I S GENERATED BY ASPIRATION OF N2O4 INTO WATER. NASA WIWPS# 3					

SITE NAME

NASA JSC WHITE SANDS TEST FACILITY

NASA ROAD

LAS CRUCES, NM 88012

EPA ID NO: NM8800019434

FORM
GMU.S. ENVIRONMENTAL
PROTECTION AGENCY
2001 Hazardous Waste ReportWASTE GENERATION
AND MANAGEMENT

Sec. 1	A. Waste Description OXIDIZER CONTAMINATED WATER				
B. EPA Hazardous Waste Code D002			C. State Hazardous Waste Code		
D. Source Code G01 Management Method Code for Source code G25		E. Form Code W105	F. RCRA radioactive mixed N	G. Quantity Generated in 2001 378.500000	H. UOM 6 Density 1.00 spec.gra
Sec. 2	C. Was any of this waste managed on-site: Yes				
ON-SITE PROCESS SYSTEM 1			ON-SITE PROCESS SYSTEM 2		
On-site Management Method code H122		Quantity treated, disposed, or recycled on-site in 2001 378.500000		On-site Management Method code *****	
Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal, or recycling? No				
Site #	B. EPA ID No. of facility waste was shipped to	C. Off-site Management Method Code shipped to		D. Total quantity shipped in 2001	
Comments NASA WIWPS# 20-04-74, 30-01-02, 30-01-37, 40-01-02					

SITE NAME

NASA JSC WHITE SANDS TEST FACILITY

NASA ROAD

LAS CRUCES, NM 88012

EPA ID NO: NM8800019434

FORM
GMU.S. ENVIRONMENTAL
PROTECTION AGENCY
2001 Hazardous Waste ReportWASTE GENERATION
AND MANAGEMENT

Sec. 1	A. Waste Description INORGANIC LABORATORY WASTE				
B. EPA Hazardous Waste Code D002			C. State Hazardous Waste Code		
D. Source Code G22 Management Method Code for Source code G25		E. Form Code W119	F. RCRA radioactive mixed N	G. Quantity Generated in 2001 1,895.500000	H. UOM 6 Density 1.00 spec.gra
Sec. 2	C. Was any of this waste managed on-site: Yes				
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2			
On-site Management Method code H122		Quantity treated, disposed, or recycled on-site in 2001 1,892.500000		On-site Management Method code *****	
Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal, or recycling? No				
Site #	B. EPA ID No. of facility waste was shipped to	C. Off-site Management Method Code shipped to		D. Total quantity shipped in 2001	
Comments ADDITIONAL CODE INFORMATION: FORM CODE; W119 INORGANIC LABORATORY WASTE WITH POSSIBLE ACID, CAUSTIC, METAL AND DISSOLVE					

SITE NAME

NASA JSC WHITE SANDS TEST FACILITY

NASA ROAD

LAS CRUCES, NM 88012

EPA ID NO: NM8800019434

FORM
GMU.S. ENVIRONMENTAL
PROTECTION AGENCY
2001 Hazardous Waste ReportWASTE GENERATION
AND MANAGEMENT

Sec. 1	A. Waste Description SPENT OAKITE 90 CLEANING SOLUTION				
B. EPA Hazardous Waste Code D002			C. State Hazardous Waste Code		
D. Source Code G02 Management Method Code for Source code G25		E. Form Code W110	F. RCRA radioactive mixed N	G. Quantity Generated in 2001 37.900000	H. UOM 6 Density 1.00 spec.gra
Sec. 2	C. Was any of this waste managed on-site: Yes				
ON-SITE PROCESS SYSTEM 1			ON-SITE PROCESS SYSTEM 2		
On-site Management Method code H122		Quantity treated, disposed, or recycled on-site in 2001 37.900000		On-site Management Method code *****	
Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal, or recycling? No				
Site #	B. EPA ID No. of facility waste was shipped to	C. Off-site Management Method Code shipped to		D. Total quantity shipped in 2001	
Comments NASA WIWPS# 20-01-52					



U.S. ENVIRONMENTAL
PROTECTION AGENCY
2001 Hazardous Waste Report

**FORM
GM**

**WASTE GENERATION
AND MANAGEMENT**

SITE NAME
NASA JSC WHITE SANDS TEST FACILITY
NASA ROAD
LAS CRUCES, NM 88012
EPA ID NO: NM8800019434

Sec. 1	A. Waste Description SPENT ACIDIC CLEANING SOULTION				
B. EPA Hazardous Waste Code D002			C. State Hazardous Waste Code		
D. Source Code G02 Management Method Code for Source code G25		E. Form Code W105	F. RCRA radioactive mixed N	G. Quantity Generated in 2001 3,803.900000	H. UOM 6 Density 1.00 spec.gra

Sec. 2	C. Was any of this waste managed on-site: Yes	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method code H122	Quantity treated, disposed, or recycled on-site in 2001 3,803.900000	On-site Management Method code Quantity treated, disposed, or recycled on-site in 2001 *****

Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal, or recycling? No		
Site #	B. EPA ID No. of facility waste was shipped to	C. Off-site Management Method Code shipped to	D. Total quantity shipped in 2001

Comments	NASA WIWPS# 20-01-41, 20-01,51
-----------------	--------------------------------

SITE NAME

NASA JSC WHITE SANDS TEST FACILITY

NASA ROAD

LAS CRUCES, NM 88012

EPA ID NO: NM8800019434

FORM
GMU.S. ENVIRONMENTAL
PROTECTION AGENCY
2001 Hazardous Waste ReportWASTE GENERATION
AND MANAGEMENT

Sec. 1	A. Waste Description SPENT ECHANTS				
B. EPA Hazardous Waste Code D002			C. State Hazardous Waste Code		
D. Source Code G03 Management Method Code for Source code G25		E. Form Code W105	F. RCRA radioactive mixed N	G. Quantity Generated in 2001 3.800000	H. UOM 6 Density 1.00 spec.gra
Sec. 2	C. Was any of this waste managed on-site: Yes				
ON-SITE PROCESS SYSTEM 1			ON-SITE PROCESS SYSTEM 2		
On-site Management Method code H122		Quantity treated, disposed, or recycled on-site in 2001 3.800000		On-site Management Method code *****	
Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal, or recycling? No				
Site #	B. EPA ID No. of facility waste was shipped to	C. Off-site Management Method Code shipped to		D. Total quantity shipped in 2001	
Comments NASA WIWPS# 20-02-01					



U.S. ENVIRONMENTAL
PROTECTION AGENCY
2001 Hazardous Waste Report

**FORM
GM**

**WASTE GENERATION
AND MANAGEMENT**

Sec. 1	A. Waste Description SPENT TINPOSIT SOLUTION LT-26				
B. EPA Hazardous Waste Code D002			C. State Hazardous Waste Code		
D. Source Code G06 Management Method Code for Source code G25		E. Form Code W105	F. RCRA radioactive mixed N	G. Quantity Generated in 2001 18.900000	H. UOM 6 Density 1.00 spec.gra
Sec. 2	C. Was any of this waste managed on-site: Yes				
ON-SITE PROCESS SYSTEM 1			ON-SITE PROCESS SYSTEM 2		
On-site Management Method code H122		Quantity treated, disposed, or recycled on-site in 2001 18.900000		On-site Management Method code Quantity treated, disposed, or recycled on-site in 2001 *****	
Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal, or recycling? No				
Site #	B. EPA ID No. of facility waste was shipped to	C. Off-site Management Method Code shipped to	D. Total quantity shipped in 2001		
Comments ADDITIONAL CODE INFORMATION: SOURCE CODE G06; COATING CIRCUIT BOARDS. NASA WIWPS# 20-05-06					



U.S. ENVIRONMENTAL
PROTECTION AGENCY
2001 Hazardous Waste Report

SITE NAME

NASA JSC WHITE SANDS TEST FACILITY
NASA ROAD
LAS CRUCES, NM 88012

EPA ID NO: NM8800019434

**FORM
GM****WASTE GENERATION
AND MANAGEMENT**

Sec. 1	A. Waste Description SPENT X-RAY/PHOTOGRAPHIC FIXER SOLUTIONS				
B. EPA Hazardous Waste Code D011			C. State Hazardous Waste Code		
D. Source Code G07 Management Method Code for Source code G25		E. Form Code W119	F. RCRA radioactive mixed N	G. Quantity Generated in 2001 1,458.100000	H. UOM 6 Density 1.00 spec.gra
Sec. 2	C. Was any of this waste managed on-site: Yes				
ON-SITE PROCESS SYSTEM 1			ON-SITE PROCESS SYSTEM 2		
On-site Management Method code H122		Quantity treated, disposed, or recycled on-site in 2001 1,458.100000	On-site Management Method code *****		
Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal, or recycling? No				
Site #	B. EPA ID No. of facility waste was shipped to	C. Off-site Management Method Code shipped to	D. Total quantity shipped in 2001		
Comments ADDITIONAL CODE INFORMATION: FORM CODE; W119 PHOTOGRAPHIC FILM DEVELOPING FIXER SOLUTION WITH LESS THAN 75 PPM SILVER.					

SITE NAME

NASA JSC WHITE SANDS TEST FACILITY

NASA ROAD

LAS CRUCES, NM 88012

EPA ID NO: NM8800019434

**FORM
GM**U.S. ENVIRONMENTAL
PROTECTION AGENCY
2001 Hazardous Waste Report**WASTE GENERATION
AND MANAGEMENT**

Sec. 1	A. Waste Description FUEL (HYDRAZINES) DILUTED IN WATER				
B. EPA Hazardous Waste Code P068 U133 U098 U099			C. State Hazardous Waste Code		
D. Source Code G19 Management Method Code for Source code G25		E. Form Code W113	F. RCRA radioactive mixed N	G. Quantity Generated in 2001 26,212.000000	H. UOM 3 Density 0.00 lb./gal.
Sec. 2	C. Was any of this waste managed on-site: No				
ON-SITE PROCESS SYSTEM 1			ON-SITE PROCESS SYSTEM 2		
On-site Management Method code Quantity treated, disposed, or recycled on-site in 2001			On-site Management Method code Quantity treated, disposed, or recycled on-site in 2001		
Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal, or recycling? Yes				
Site # 1	B. EPA ID No. of facility waste was shipped to ARD069748192	C. Off-site Management Method Code shipped to H040		D. Total quantity shipped in 2001 26,212.000000	
Comments ADDITIONAL CODE INFORMATION: SOURCE CODE; G19 SPACE SHUTTLE TESTING PROPELLANT AQUEOUS WASTES GENERATED BY TEST ARTICLE					

SITE NAME

NASA JSC WHITE SANDS TEST FACILITY

NASA ROAD

LAS CRUCES, NM 88012

EPA ID NO: NM8800019434

FORM
GMU.S. ENVIRONMENTAL
PROTECTION AGENCY
2001 Hazardous Waste ReportWASTE GENERATION
AND MANAGEMENT

Sec. 1	A. Waste Description CYANIDE BEARING WASTE				
B. EPA Hazardous Waste Code D003			C. State Hazardous Waste Code		
D. Source Code G22 Management Method Code for Source code G25		E. Form Code W119	F. RCRA radioactive mixed N	G. Quantity Generated in 2001 1.000000	H. UOM 6 Density 1.00 spec.gra
Sec. 2	C. Was any of this waste managed on-site: Yes				
ON-SITE PROCESS SYSTEM 1			ON-SITE PROCESS SYSTEM 2		
On-site Management Method code H075		Quantity treated, disposed, or recycled on-site in 2001 1.000000	On-site Management Method code H122		Quantity treated, disposed, or recycled on-site in 2001 *****
Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal, or recycling? No				
Site #	B. EPA ID No. of facility waste was shipped to	C. Off-site Management Method Code shipped to	D. Total quantity shipped in 2001		
Comments ADDITIONAL CODE INFORMATION: FORM CODE; W119 CYANIDE IN CHEMICAL STANDARDS IS NEUTRALIZED PRIOR TO ENTRY INTO THE PERMI					

SITE NAME

NASA JSC WHITE SANDS TEST FACILITY
NASA ROAD
LAS CRUCES, NM 88012

EPA ID NO: NM8800019434

**FORM
GM**

U.S. ENVIRONMENTAL
PROTECTION AGENCY
2001 Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Sec. 1	A. Waste Description PURGED GROUNDWATER				
B. EPA Hazardous Waste Code F001 F002			C. State Hazardous Waste Code		
D. Source Code G44 Management Method Code for Source code G25		E. Form Code W219	F. RCRA radioactive mixed N	G. Quantity Generated in 2001 105,601.500000	H. UOM 6 Density 1.00 spec.gra
Sec. 2	C. Was any of this waste managed on-site: Yes				
ON-SITE PROCESS SYSTEM 1			ON-SITE PROCESS SYSTEM 2		
On-site Management Method code H122		Quantity treated, disposed, or recycled on-site in 2001 105,601.500000	On-site Management Method code Quantity treated, disposed, or recycled on-site in 2001 *****		
Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal, or recycling? No				
Site #	B. EPA ID No. of facility waste was shipped to	C. Off-site Management Method Code shipped to	D. Total quantity shipped in 2001		
Comments ADDITIONAL CODE INFORMATION: FORM CODE; W219 PURGED GROUNDW ATER (RCRA INVESTIGATIVE DERIVED WASTE) WITH LOW CONCENTRATI					



U.S. ENVIRONMENTAL
PROTECTION AGENCY
2001 Hazardous Waste Report

FORM
GM

WASTE GENERATION
AND MANAGEMENT

SITE NAME

NASA JSC WHITE SANDS TEST FACILITY

NASA ROAD

LAS CRUCES, NM 88012

EPA ID NO: NM8800019434

Sec. 1	A. Waste Description MERCURY CONTAINED IN MANUFACTURED ARTICLES				
B. EPA Hazardous Waste Code D009			C. State Hazardous Waste Code		
D. Source Code G15 Management Method Code for Source code G25		E. Form Code W320	F. RCRA radioactive mixed N	G. Quantity Generated in 2001 30.000000	H. UOM 3 Density 0.00 lb./gal.
Sec. 2	C. Was any of this waste managed on-site: No				
ON-SITE PROCESS SYSTEM 1			ON-SITE PROCESS SYSTEM 2		
On-site Management Method code			On-site Management Method code		
Quantity treated, disposed, or recycled on-site in 2001			Quantity treated, disposed, or recycled on-site in 2001		
Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal, or recycling? No				
Site #	B. EPA ID No. of facility waste was shipped to	C. Off-site Management Method Code shipped to		D. Total quantity shipped in 2001	
Comments ADDITIONAL CODE INFORMATION: SOURCE CODE; G053 CLEANUP OF S PILL RESIDUES. NASA WIWPS 10-04-05, 10-04-12, 20-02-19, 20-					

SITE NAME

NASA JSC WHITE SANDS TEST FACILITY

NASA ROAD

LAS CRUCES, NM 88012

EPA ID NO: NM8800019434

**FORM
GM**U.S. ENVIRONMENTAL
PROTECTION AGENCY
2001 Hazardous Waste Report**WASTE GENERATION
AND MANAGEMENT**

Sec. 1	A. Waste Description MERCURY CONTAINING BATTERIES				
B. EPA Hazardous Waste Code D009			C. State Hazardous Waste Code		
D. Source Code G15 Management Method Code for Source code G25		E. Form Code W309	F. RCRA radioactive mixed N	G. Quantity Generated in 2001 18.200000	H. UOM 3 Density 0.00 lb./gal.
Sec. 2	C. Was any of this waste managed on-site: No				
ON-SITE PROCESS SYSTEM 1			ON-SITE PROCESS SYSTEM 2		
On-site Management Method code		Quantity treated, disposed, or recycled on-site in 2001		On-site Management Method code	
				Quantity treated, disposed, or recycled on-site in 2001	
Sec. 3	A. Was any of this waste shipped off site in 2001 for treatment, disposal, or recycling? No				
Site #	B. EPA ID No. of facility waste was shipped to	C. Off-site Management Method Code shipped to		D. Total quantity shipped in 2001	
Comments NASA WIWPS# 10-20-14, 80-04-14					

SITE NAME

NASA JSC WHITE SANDS TEST FACILITY
 NASA ROAD
 LAS CRUCES NM 88012

EPA ID NO: NM8800019434



U.S. ENVIRONMENTAL
 PROTECTION AGENCY
 2001 Hazardous Waste Report

FORM
 OI

OFF-SITE
 IDENTIFICATION

A. EPA ID No. of off-site installation or transporter LAD981055791	B. Name of off-site installation or transporter SAFETY-KLEEN (COLFAX) INC.
C. Handler Type N Generator N Transporter Y TSDR	D. Address of off-site installation Street 3763 HWY 471 City COLFAX State LA Zip 71417-

A. EPA ID No. of off-site installation or transporter TXR000074591	B. Name of off-site installation or transporter CHEMICAL TRANSPORTATION INC.
C. Handler Type N Generator Y Transporter N TSDR	D. Address of off-site installation Street City State Zip -

A. EPA ID No. of off-site installation or transporter AZD049318009	B. Name of off-site installation or transporter SAFETY-KLEEN SOUTHWEST
C. Handler Type N Generator N Transporter Y TSDR	D. Address of off-site installation Street 1340 W. LINCOLN STREET City PHOENIX State AZ Zip 85007-

A. EPA ID No. of off-site installation or transporter ARD069748192	B. Name of off-site installation or transporter ENSCO
C. Handler Type N Generator N Transporter Y TSDR	D. Address of off-site installation Street AMERICAN OIL ROAD City EL DORADO State AR Zip 71730-

A. EPA ID No. of off-site installation or transporter TXD000747394	B. Name of off-site installation or transporter Safety-Kleen Systems, Inc.
C. Handler Type N Generator Y Transporter N TSDR	D. Address of off-site installation Street 900 A HAWKINS BLVD. City El Paso State TX Zip 79915-

SITE NAME

NASA JSC WHITE SANDS TEST FACILITY
 NASA ROAD
 LAS CRUCES NM 88012

EPA ID NO: NM8800019434



U.S. ENVIRONMENTAL
 PROTECTION AGENCY
 2001 Hazardous Waste Report

FORM
 OI

OFF-SITE
 IDENTIFICATION

A. EPA ID No. of off-site installation or transporter NMD002208627	B. Name of off-site installation or transporter RINCHEM CO., INC
C. Handler Type N Generator Y Transporter N TSDR	D. Address of off-site installation Street City State Zip -

A. EPA ID No. of off-site installation or transporter OKD981588791	B. Name of off-site installation or transporter TRIAD TRANSPORT INC.
C. Handler Type N Generator Y Transporter N TSDR	D. Address of off-site installation Street City State Zip -

A. EPA ID No. of off-site installation or transporter SCR000074591	B. Name of off-site installation or transporter SAFETY-KLEEN (TG) INC.
C. Handler Type N Generator Y Transporter N TSDR	D. Address of off-site installation Street City State Zip -

A. EPA ID No. of off-site installation or transporter MOR000012948	B. Name of off-site installation or transporter R & R TRUCKING INC.
C. Handler Type N Generator Y Transporter N TSDR	D. Address of off-site installation Street City State Zip -

A. EPA ID No. of off-site installation or transporter CAT000624247	B. Name of off-site installation or transporter M P ENVIRONMENTAL
C. Handler Type N Generator Y Transporter N TSDR	D. Address of off-site installation Street City State Zip -